## Ideal Inspection (a division of Ideal Oilfield Construction Ltd.) P.O Box 1473 Brooks, Alberta T1R 1C3 Phone: 403-362-2843 Fax: 403-362-2862

## INSPECTION REPORT

Nigota A Charlingtures	Location: DaPaJo	o Construction Limited	Date: March 27, 2017
Client: 4 Star Ventures	Unit : 20499		Inspection: Magnetic Particle
Page: 1 of 1	Report: 4743		
TOTAL OF COLUMN 1			
Parts Examined: 4 ½ Casing Elevator  Surface Condition: Painted Material Temperature: 8° Celsius			
Surface Condition: Painted		Code: ASME Section V, ASTM E709	
Procedure: MPI-DPJ-001		Code. Admit decision 1)	
Equipment: Parker B 310 Contour Probe			
Method: Magnetic Particle, AC Continuous, Wet Colour Contrast Method			
Test Medium: Magnaglo 14AM prepared bath			
Test Results: NO DEFECTS WERE FOUND AT THE TIME OF	THIS INSPECTION	Engineer's Approval:	May 23, 2017
Photos:			
		3 Signature: 2	Assistant: Travis Bungay
Technician: Bryan Hoskins	CGSB #: 19053	3 Signature:	
Repairs Yes No	N/A X		Acceptable For Service Yes X No