


415



Ideal Inspection

(a division of Ideal Oilfield Construction Ltd.)
P.O Box 1473
Brooks, Alberta
T1R 1C3
Phone: 403-362-2843 Fax: 403-362-2862

INSPECTION REPORT

Client: Four Star Ventures	Location: DaPaJo Construction Limited	Date: May 31, 2012
P.O. :	Work Order : 639e	Report : 3550
Page : 1 of 1	Rig or Unit :	Inspection: Magnetic Particle
Parts Examined: 4 1/2" Web Wilson H50 50 Ton elevator		S/N: 37522 EL15007 HOU93376
Surface Condition: Painted	Material Temperature: 20° Celsius	
Procedure: MPI-DPJ-001	Code: ASME Section V, ASTM E709	
Equipment: Parker B 310 Contour Probe, PM-50 Permanent Magnets, Spectroline Model C-100 Super High Intensity Black Light Lamp		
Method: Magnetic Particle, Wet fluorescent Colour Contrast Method		
Test Medium: Ardrex 8800a Fluorescent Magnetic Particle Suspension		

Test Results:

No defects found at time of inspection.

Engineer's Approval:

Photos:



Technician: John Frances	CGSB #: 7062	Signature: <i>J.F.</i>	Assistant: Tyler Nevison
Repairs Complete	Yes <input type="checkbox"/> No <input type="checkbox"/> N/A <input type="checkbox"/> X <input type="checkbox"/>	Acceptable For Service	Yes <input type="checkbox"/> X <input type="checkbox"/> No <input type="checkbox"/>



PERMIT TO PRACTICE FIRTH ENGINEERING LTD.	
Signature: <i>Mark Firth</i>	
Date: 31 May 12	
PERMIT NUMBER: P 6554	
The Association of Professional Engineers, Geologists and Geophysicists of Alberta	