


Ideal Inspection
 (a division of Ideal Oilfield Construction Ltd.)
 P.O Box 1473
 Brooks, Alberta
 T1R 1C3
 Phone: 403-362-2843 Fax: 403-362-2862

INSPECTION REPORT

Client: Four Star Ventures	Location: DaPaJo Construction Limited	Date: May 31, 2012
P.O. :	Work Order : 639a	Report : 3546
Page : 1 of 1	Rig or Unit :	Inspection: Magnetic Particle
Parts Examined: 8 5/8" Web Wilson 50 Ton elevator D950		S/N: EDM069255610016LT
Surface Condition: Painted	Material Temperature: 20° Celsius	
Procedure: MPI-DPJ-001	Code: ASME Section V, ASTM E709	
Equipment: Parker B 310 Contour Probe, PM-50 Permanent Magnets, Spectroline Model C-100 Super High Intensity Black Light Lamp		
Method: Magnetic Particle, Wet fluorescent Colour Contrast Method		
Test Medium: Ardrox 8800a Fluorescent Magnetic Particle Suspension		

Test Results:	Engineer's Approval:
No defects found at time of inspection.	



Technician: John Frances	CGSB #: 7062	Signature:	Assistant: Tyler Nevison
Repairs Complete	Yes <input type="checkbox"/> No <input type="checkbox"/> N/A <input type="checkbox"/> X <input type="checkbox"/>	Acceptable For Service Yes <input type="checkbox"/> X <input checked="" type="checkbox"/> No <input type="checkbox"/>	



PERMIT TO PRACTICE
FIRTH ENGINEERING LTD.

Signature: *[Signature]*
 Date: *31 May 12*

PERMIT NUMBER: P 6554
 The Association of Professional Engineers,
 Geologists and Geophysicists of Alberta