

January 18, 2013

4 Star Ventures Ltd.
Po Box 193
Gull Lake, Saskatchewan
S0N 1A0

Certificate of Conformance


Rig No.: N/A
Equipment: Casing Elevator - 150 Ton
Model: 13 3/8" SLX-150 Side Door
Customer P.O.: Keith
Serial No.: 80774
Inspection Report No.: H-N/A
Alco Sales/Engineering No.: 29797-1-E
APEGGA Permit to Practice No.: P10702
Alco Shop Work Order # : N/A

This document specifies that all parts and/or assemblies for the equipment referenced above are sold under the manufacturer's warranty.

The above referenced items are to be used according to the manufacturer's directions and ratings. Alco assumes no responsibility for defective parts or assemblies or any costs associated with their repair due to normal use or misuse.

The manufacture's documentation provided for the item(s) listed above indicate conformance to the American Petroleum Institute's (API) section 8C . The item(s) have been load tested to 1.5 times the rating.

A CAODC Recommended Practice Level IV inspection is typically required after: 500 operating days.



January 17, 2013

4 Star Ventures Ltd.
Po Box 193
Gull Lake, Saskatchewan
S0N 1A0

Certificate of Conformity

Rig No.:	N/A
Equipment:	<i>Alco Elevator Reducing Bushing</i>
Model:	<i>13 3/8" - 11 3/4" - 150 Ton</i>
Customer P.O.:	N/A
Serial No.:	N/A
Inspection Report No.:	<i>H-29031</i>
Alco Sales/Engineering No.:	<i>29797-E</i>
APEGGA Permit to Practice No.:	<i>P10702</i>
Alco Shop Work Order # :	<i>23815</i>

This document certifies that all parts and /or assemblies for the Alco equipment referenced above have been manufactured using new materials and inspected in accordance with the customer's purchase order, as well as all applicable Alco Inc. specifications and procedures.

All material acceptances, dimensional inspections, proof and function tests and nondestructive testing inspections were performed by Alco Inc. qualified personnel and meet Alco Inc. specifications as well as those required by API Specification 8A and 8C.

