



Borza Inspections Ltd.

5713 - 17 Street, Edmonton, Alberta, Canada T6P 1S4
Bus. (780) 944-2857 • Fax: (780) 440-2147
24 Hour Service
Edmonton, AB • Fort Nelson, BC • Fort St. John, BC

ISO 9003 - #97-898

May 30, 2003

Sell's Power Tongs
Box 193
Gull Lake, Saskatchewan
SON 1A0

CERTIFICATION

Equipment: BJ Elevator Assembly
Borza Inspections Ltd. Stamp No.: M62741
Model: 4 1/2" - - 90° - TA - 100 Ton
Owner: Sell's Power Tongs
Repair Facility: Clem Industrial Machine (W.O. 50460)
Borza File No's: B9110/M62741

We performed our engineering examination of this elevator assembly on May 22, 2003 at Clem Industrial Machine. The elevator assembly was completely disassembled and sandblasted

Borza technicians provided magnetic particle inspection services. Final NDT inspection revealed no defects. New pins were supplied by Clem Industrial Machine.

As a result of our inspections and review of repairs, we believe that this elevator assembly may be safely returned to service within the manufacturer's original specifications.

This certification is valid for 500 operating days as per CAODC T-94-1/RP-2.0 or until the elevator assembly is damaged by handling or operation.

