

Ideal Inspection
 (a division of Ideal Oilfield Construction Ltd.)
 P.O Box 1473
 Brooks, Alberta
 T1R 1C3
 Phone: 403-362-2843 Fax: 403-362-2862


411

INSPECTION REPORT

Client: 4 Star Ventures	Location: DaPaJo Construction Limited	Date: March 27, 2017
Page: 1 of 1	Unit : 106108	Inspection: Magnetic Particle
Work Order: 2822C	Report: 4745	
Parts Examined: 4 1/2 Casing Elevator		
Surface Condition: Painted	Material Temperature: 8° Celsius	
Procedure: MPI-DPJ-001	Code: ASME Section V, ASTM E709	
Equipment: Parker B 310 Contour Probe		
Method: Magnetic Particle, AC Continuous, Wet Colour Contrast Method		
Test Medium: Magnaglo 14AM prepared bath		


Test Results:
NO DEFECTS WERE FOUND AT THE TIME OF THIS INSPECTION

Engineer's Approval:



[Signature]
 May 23, 2017

Photos:



Technician: Bryan Hoskins	CGSB #: 19053	Signature: <i>[Signature]</i>	Assistant: Travis Bungay
Repairs Complete	Yes <input type="checkbox"/> No <input type="checkbox"/> N/A <input type="checkbox"/> X <input type="checkbox"/>	Acceptable For Service	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>