



ALCO INC. HEAD OFFICE
6925 · 104 Street, Edmonton, Alberta T6H 2L5
Office: (780) 435-3502
Website: www.alcoinc.ca

June 15, 2017

4 Star Ventures Ltd.
Po Box 193
Gull Lake, Saskatchewan
S0N 1A0

Certificate of Conformance

CUSTOMER:	4 Star Ventures Ltd.
CUSTOMER EQUIPMENT # :	41103
CUSTOMER RIG # :	N/A
EQUIPMENT DESCRIPTION:	RT Center Latch Casing Elevator
EQUIPMENT RATING:	7", TA-100 Ton, 100 Ton Rating (88964-daN)
INSPECTION COMPANY / REPORT #:	Alco / H-N/A
ALCO ENGINEERING FILE # :	55226-1-E
ALCO WORK ORDER # :	55226-1

This document specifies that all parts and/or assemblies for the equipment referenced above are sold under the manufacturer's warranty.

The above referenced items are to be used according to the manufacturer's directions and ratings. Alco assumes no responsibility for defective parts or assemblies or any costs associated with their repair due to normal use or misuse.

Manufacture's documentation indicate a load test to 1.5 times this component's rating has been done. Material ductility requirements conform to those specified by the American Petroleum Institute's (API) section 8c.

A CAODC Recommended Practice Level IV inspection is typically required after: 6 years.

Brian Kulak, P.Eng
Sr. Engineer
Alco Inc.

